FIRE RISK ASSESSMENT - 2024

Goring United Reformed Church

Barrington Road, Goring by Sea, Worthing BN12 4EA

Premises Description Place of Christian Worship. Hall and Sanctuary Lettings

Hours when generally occupied. 8.00am—11.00pm

Maximum persons at any one time 250

Responsible Persons GURC Elders
Position Church Leaders
Telephone Number 01903 600260

Building Owner The United Reformed Church

Tavistock Place, London

0208 688 3730

Telephone Number

Assessment by - Bett Swierk

Assessment date - 04/09/2024

Items listed in Summary completed.

Next assessment due

Oct 2025

	Sources of ignition	Υ	N
1	Electrical equipment testing and flexes safe - Visual checks in the last 12mths?	/	
2	Electrical equipment fixed and PAT in the last 5 years, and certificates issued?	<i>'</i>	
3	Gas servicing of all appliances, and certificates issued?	·	
4	Portable, Fixed Heating & Cooking Hobs kept away from combustibles	, ,	
5	Safe storage of combustibles, flammable liquids and paints.	~	
	Fire alarms and detection		
6	Is a procedure in place to check the alarms on a weekly basis	/	
7	Are all call points and/or extinguishers free from obstruction?	•	
8	Has the alarm system been tested in the last 12 months?	✓	
9	Have the extinguishers been tested in the last 12 months?	✓	
10	Have the stewards been reminded on what to do in case of an alarm?	~	
11	Has a fire drill been carried out in the last 12 months?		/
12	Are the people hiring our premises aware of actions in case of fire?	~	
	Moons of Essano with Signago and Lighting Boguiroments		
	Means of Escape with Signage and Lighting Requirements		
13	Are there alternative and sufficient exits from all areas of the premises?	✓	
14	Are all escape routes unobstructed and free from combustibles?	•	
15	Notice is in place on choir vestry door. 'Keep unlocked when occupied' Checked?		
16	Are the premises fitted with suitable and sufficient exit signage?	•	
17	Is the external meeting place sign in place? (Faded when checked 2024)	~	
18	Is all emergency lighting in working order?	✓	
19	Have all escape routes been checked in last 12 months?	/	

	General	Υ	N
20	Are the premises reasonably secure during the hours of darkness?	/	
21	Is CCTV in place and working? Checked?	✓	
22	Is there a reasonable standard of external and movement detection security lighting?	~	
23	Are wheelie bins remote from the building?		✓
	Are the following records up to date :-		
24a	Fire alarm weekly tests, staff training and fire drills	~	
24b	Emergency lighting	•	
24c	Electrical Portable Appliance Testing/Visual testing	•	
24d	Gas Servicing	•	
25	Is the Fire Action Plan displayed at each exit point?	✓	
26	The Action plan gives information on the following - Action on discovering a fire, location of assembly point, how to raise the alarm, action on hearing the alarm, routes to exit building and to reach assembly point.	•	

SUMMARY

Where 'NO' has been ticked in the above boxes, complete this Summary section below.

No. Action required Date completed

11 Next fire drill due in January 2025

Wheelie bins. It is not practical for these to be remote from the building; stored in area where they can be seen and removed if needed.