

Inspection Certificate

t. 01992 893 498

e. servicedesk@morganfire.co.uk



Customer	Goring United Reformed Church	Call Type	Preventative Maintenance
Customer No.	GORI401	System Type	Portable Extinguishers
Customer Reference		Schedule Type	Annual Inspection
		Police Status	U
Site Name	Goring United Reformed Church	Call Number	3490956
		Call Reason	Preventative Maintenance
Site ID	MFP20233656	Contact	
Address	Barrington Road		
	Goring By Sea	Property Ref	OO Number: 514
	West Sussex		
Postcode	BN12 4EA	Telephone No.	01903 260568/243194

Remarks

Preventative Maintenance : Annual Inspection

Notes :

Actions

Annual fire extinguisher service complete.

Quantity	Description
2	6ltr Water Extinguisher
2	New Extinguisher / Commission To Bs5306
2	Environmental Disposal Extinguishers
3	Corrective action Sticker (SINGLE)
1	DIS-FB Environmental Disposal Fire Blanket
6	Gauge Dots Each
6	Pressure Gauge Test
13	Anti-vandal tags
5	Nitrile O Ring 9.25 x 1.78
1	1.2m x 1.2m Fire Blanket

Checklist

Item	Checked	Remarks
Please identify if any of the following hazards are present.0		
If so, please ensure the relevant risk assessments have been read, understood, and carried out. These are to be read in addition to the RAMs attached to this job.		
Working At Height (COM-ASS-TRA-04)	0	
Electrical Isolation (COM-ASS-TRA-32)	0	
Confined Space (COM-ASS-TRA-34)	0	
Compressed Gas (COM-ASS-TRA-95)	0	
If this address was difficult to find please obtain the What3Words for this location	0	
Extinguishers inspected and serviced in accordance with P		Yes

BS5306 Part 3

3L Water	0	
6L Water	P	3 x serviced
9L Water	P	5 x serviced
3L Water Mist	0	
6L Water Mist	0	
9L Water Mist	0	
2L AFFF	0	
3L AFFF	0	
6L AFFF	0	
9L AFFF	0	
2kg CO2	P	5 x serviced
5kg CO2	0	
1kg Dry Powder	0	
2kg Dry Powder	0	
3kg Dry Powder	0	
4kg Dry Powder	0	
6kg Dry Powder	0	
9kg Dry Powder	0	
2L Wet Chemical	0	
3L Wet Chemical	0	
6L Wet Chemical	0	
Tamper Tags Changed	0	
O Rings Changed	0	
Gauge Test Carried Out	0	
Fire Blanket	P	2 x insp
Hose Reel	0	
Other sizes/types Not Listed Above	0	
All product has been serviced and passed and no failures are present	P	Yes
Have any extinguishers been condemned? If yes, please provide details.	P	2 x 9lt Waters blown liner 1 x Fire blanket
Does the layout still comply with BS5306-8? If not, specify the reason(s) and further action	P	Yes
Is the FRA available and reviewed for compliance with BS5306-3?		
If not available, has the customer been advised that it is their responsibility to hold a FRA	0	
Is the fire log book available and has it been filled in?	0	
If no log book is available, has a new one been left on site?	0	
Are all areas of the site available for access at the time of service? If not, detail the areas not available for access	0	
Equipment listing has changed. Office to amend.	0	
Equipment Quotation Required	0	
Service Quotation Required	0	
Is there appropriate Company signage/ asset label(s) / label(s) affixed to the relevant equipment? (Y/N)	P	Yes
Waste removed from site?	0	
Please obtain email address for engineer dockets to be sent to. There can be multiple email addresses	P	bett.swierk@hotmail.com

Please obtain email address for invoices to be sent to. P bett.swierk@hotmail.com
There can be multiple email addresses

Risk Assessment

Item	Checked	Remarks
I confirm that I have access to the RAMS specific to the tasks relating to the job assigned, will work in conjunction with the RAMS. If I am unable to undertake the work I will refer to my line manager and/or escalate to compliance team for guidance.	P	

Fault Code**Fault Group**

Declaration

The Company certify that, unless otherwise stated, the inspection has been carried out in accordance with BS:5306-3: 2017 and part 8 2012

It is the responsible person's responsibility to carry out visual inspections of all extinguishers at regular intervals.

It is the responsible person's responsibility to ensure an UpToDate Fire Risk Assessment is carried out and is available.

It is the responsible person's responsibility that a fire logbook is kept for the purpose of recording all events that occur in respect of the extinguishers.

It is the responsible person's obligation under fire legislation to provide an appropriate level of fire-fighting equipment at all times and it has periodic inspections.

Arrived On Site 10:50:00 14/11/2024

Time Left Site 11:03:00 14/11/2024

Engineers Declaration


I confirm that the work undertaken is, to the best of my knowledge, in accordance with the dynamic risk assessment undertaken and to the recommendations of British Standards and that all areas of non conformity have been brought to the attention of the Customer.

Customer Satisfaction

I confirm that there has been no 3rd party interference with System since the last attendance of the Company. The work undertaken has been completed to my satisfaction and the Engineer has brought to my attention any/all areas of non conformity. I agree that the work should be charged at the standard rates of the Company.

Engineer Name Mark Wadlow

Engineer Signature



Customer Name No Body On Site To Sign

Customer Signature



All work undertaken is subject to the Terms & Conditions of the Company